FIG.1




FIG. 2




FIG. 3





FIG. 4



O: POSITIONS OF ARRANGING SPACERS 19

FIG. 5





FIG. 6










FIG. 7












FIG. 8




FIG. 9





FIG. 10



O : POSITIONS OF ARRANGING SPACERS 19



FIG. 11






FIG. 12



 \square : Positions of arranging spacers 19

FIG. 13



The state of the s